



Florida  
Oceanographic  
Society



## Before

How the St. Lucie Inlet looks when there are no discharges.



Edge of  
plume

## After

How the St. Lucie Inlet looks during discharges. This picture was taken May 3, 2000. Notice the sediment plume extending well out into the ocean. The area to the south of the inlet is a coral reef in St. Lucie Inlet State Park.

Pictures courtesy Chris Perry © 2001

890 NE Ocean Blvd. ❁ Stuart, FL 34996 ❁ (561) 225-0505 ❁ [www.fosusa.org](http://www.fosusa.org)



Florida  
Oceanographic  
Society



**Inside St. Lucie Inlet August 10, 2001**  
700 Acres of Seagrass Beds  
Brown color from water discharged from C-23 & C-24



**St. Lucie Inlet August 10, 2001**  
Brown color from water discharged from C-23 & C-24

Pictures courtesy Chris Perry © 2001



Florida  
Oceanographic  
Society



**C-23 Canal (S-48) on August 10, 2001**  
Discharging into the St. Lucie River Estuary



**C-24 Canal (S-49) on August 10, 2001**  
Discharging into the St. Lucie River Estuary

Pictures courtesy Chris Perry © 2001